Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7





Fig. 8



CONTACT BETWEEN THE GROOVE OF THE HOUSING AND THE OUTER ROLLER AT THE OPPOSITE SIDE OF THE LOADED SIDE

Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19

